



!! URGENT !!

Date: 01 October 2025

Subject: Dourados, Brazil
Dourados (SBDO)
Multiple procedures
Cycle 2510

Procedure coding outdated

Jeppesen NavData for cycle 2510, effective 02 October 2025, contains incorrect data for Dourados; Dourados, Brazil (SBDO). BRAZIL - MAP AMDT 010-25 - 02 OCT 25 was received after the ICAO specified date for aeronautical information publication.

NDB A - Final course and first leg of missed approach should read **148°**.

NDB Rwy 06 - Final course and first leg of missed approach should read **048°**.

NDB Rwy 24 - Fix DO037 should read: **DO005**.

RNP Rwy 06 - SDF DO101, altitude **2280'** is missing from database, FAF altitude should read: **2960'**.

RNP Rwy 24 - FAF altitude should read: **3270'**, **SDF DO102**, altitude **2350'** missing from database, VNAV angle should read: **3.00°**.

EGALI 2A RNAV DEP [EGAL2A] - speed restrictions at **DO034** & **DO036** withdrawn,

IMBUP 2A RNAV DEP [IMBU2A] - distance between **RWY** & **IMBUP** should read 3,2NM

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2511, effective 30 October 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jepesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

SBDO_2510