

Radio Tuning Unit (RTU-4000/-4010/-4020) Product Discontinuance

Ref. No. 2013-109M

Pub Date 09/2013

Effective October 1, 2013, Rockwell Collins is announcing the discontinuance of production on the Cathode Ray Tube (CRT) based Radio Tuning Unit (RTU), specifically the RTU-4000, RTU-4010 and RTU-4020. Rockwell Collins will continue to provide repair services for these products on a parts available basis. Last time buy orders will be accepted until September 30, 2014.

RADIO TUNING UNIT– DISCONTINUED PART NUMBER

Equipment Type	Discontinued Part Number
RTU-4000	622-9852-xxx (All Statuses)
RTU-4010	822-0002-xxx (All Statuses)
RTU-4020	822-0002-xxx (All Statuses)

To help ensure maximum operation of the aircraft Rockwell Collins is encouraging our customers to be proactive in planning their RTU updates. The replacement unit is the RTU-42X0 which features a Liquid Crystal Display (LCD) technology and is available today. To help you upgrade the RTU in the aircraft, Supplemental Type Certificates (STCs) or AML STCs are available for many platforms.

Rockwell Collins can assist operators in determining the proper RTU replacement unit.

As a Rockwell Collins dealer, reference the RTU 42X0 installation manual part number 523-0780424 to determine the replacement. As an owner, please consult your Rockwell Collins Authorized Dealer or contact your Rockwell Collins Regional Sales Manager/ Customer Support Engineer (CSE).



How can we help?

Please call Rockwell Collins Customer Support at +1.319.295.5000.

For more information contact:

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
+1.319.295.4085
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com