

# Electronic Flight Display (EFD) 85, 85(A), 85(M), and 85(W) Production Discontinuance

Ref. No. 2014-132M  
 Pub Date 09/2014

At Rockwell Collins, we appreciate your selection of our products for your aircraft, and strive to provide you with the best quality parts and service. Occasionally, advancements in the technologies we offer our customers or the availability of parts and components, necessitate that we cease production and phase out the support of older solutions. This is the case with the Electronic Flight Display (EFD) 85, 85(A), 85(M) and 85(W).

Effective September 1, 2014, Rockwell Collins is announcing the discontinuance of production of the Cathode Ray Tube (CRT) based Electronic Flight Display (EFD), specifically the EFD-85, EFD-85(A), EFD-85(M), and EFD-85(W). Rockwell Collins will continue to provide repair services for these products on a parts available basis.

## ELECTRONIC FLIGHT DISPLAY– LAST TIME BUY PRODUCTION

Last time buy orders will be accepted until December 1, 2014, or until available components are consumed. All deliveries must be taken on or before December 1, 2015.

Equipment Type	Last Time Buy Part Number
EFD-85	622-6020-021, -121
EFD-85	827-5745-002

## ELECTRONIC FLIGHT DISPLAY– DISCONTINUED PRODUCTION

Effective September 1, 2014, the following part numbers are no longer available for purchase as new equipment:

Equipment Type	Discontinued Part Number
EFD-85	622-6020-001, 002, -011, -012, -122, -501, -502, -503
EFD-85	827-5745-102, -103
EFD-85(A)	622-6464-xxx
EFD-85(A)	827-0375-xxx
EFD-85(M)	822-1000-xxx
EFD-85(W)	822-0649-xxx

To help ensure maximum operation of the aircraft, Rockwell Collins is encouraging our customers to be proactive in planning for the discontinuance. Our recommended replacement solution is to upgrade your aircraft with our Pro Line 21 LCD flight deck display.

For Supplemental Type Certificate (STC) information reference the table below:

Aircraft Make/Model	Replacement Solution	STC Information
Beechcraft King Air Model C90	Pro Line 21 IDS with Engine Instrument Display and IFIS-5000	Hawker Beechcraft Corporation SA01447WI-D
Beechcraft King Air Model B200	Pro Line 21 IDS with Engine Instrument Display and IFIS-5000	Rockwell Collins - SA01268WI-D or Hawker Beechcraft Corporation SA01193WI-D
Beechcraft King Air Model 300/ B300/B300C	Pro Line 21 IDS with Engine Instrument Display and IFIS-5000	Rockwell Collins - SA01267WI-D or Hawker Beechcraft Corporation SA01177WI-D
Piaggio P-180 Avanti	Pro Line 21 IDS with Engine Instrument Display and IFIS-5000	Rockwell Collins - SA02327CH-D
MA-60	Not Affected	
Hawker 800A, 800B, 800XP	Pro Line 21 IDS with Engine Instrument Display and IFIS-5000	Rockwell Collins - ST02410CH-D or Duncan Aviation - SA02410CH-D or Hawker Beechcraft Corporation - ST01331WI-D or Hawker Beechcraft Corporation - ST01342WI or Raytheon Aircraft Company - ST01342WI-D
Learjet 55	Pro Line 21 IDS with Engine Instrument Display and IFIS-5000	STC Required

For assistance in determining the proper replacement, please contact your Rockwell Collins Authorized Dealer or Rockwell Collins Regional Sales Manager/ Customer Support Engineer (CSE) for more information.

How can we help?  
Please call Rockwell Collins Customer Support at +1.319.295.5000.

For more information, contact:

Rockwell Collins  
400 Collins Road NE  
Cedar Rapids, Iowa 52498  
+1.319.295.4085  
email: [csmarketing@rockwellcollins.com](mailto:csmarketing@rockwellcollins.com)  
[www.rockwellcollins.com](http://www.rockwellcollins.com)