

Production Discontinuance Bulletin

Select TDR-94/94D Mode S transponders – not applicable to latest DO-260B products

Summary

Rockwell Collins will be discontinuing production of the part numbers listed below due to market conditions and incremental product improvements. No new deliveries of the TDR-94D models listed below will be made after September 30, 2017. No new deliveries of the TDR-94 models listed below will be made after July 1, 2018. Orders for these TDR-94 products must be made no later than April 1, 2018.

NOTE: This bulletin does not affect the ADS-B Out DO-260B compliant -501 (fixed wing) or -551 (rotary wing) TDR-94/94D transponders or the DO-260A compliant TDR-94 transponder.

Am I affected?

The following parts will discontinue production. Products not listed will remain in production.

Existing		Replacement	
Product	Part number	Type	Part Number
TDR-94D	622-9210-108	TDR-94D	622-9210-412
TDR-94D	622-9210-408	TDR-94D	622-9210-412
TDR-94D	622-9210-409	TDR-94D	622-9210-412
TDR-94D	622-9210-410	TDR-94D	622-9210-412
TDR-94D	622-9210-411	TDR-94D	622-9210-412
TDR-94	622-9352-004	TDR-94	622-9352-501
TDR-94	622-9352-005	TDR-94	622-9352-501
TDR-94	622-9352-006	TDR-94	622-9352-501
TDR-94	622-9352-007	TDR-94	622-9352-501
TDR-94	622-9352-008	TDR-94	622-9352-501
TDR-94	622-9352-500	TDR-94	622-9352-501
TDR-94	622-9352-550	TDR-94	622-9352-551

Rockwell Collins may still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

For the TDR-94D:

1. Purchase the latest DO-260A compliant TDR-94D (622-9210-412)

The -412 is the newest of the DO-260A compliant TDR products and has the latest product improvements. Rockwell Collins has received an FAA letter of equivalency (L115W-16-618) to approve the 622-9210-412 as a direct TSO replacement.

2. Purchase the DO-260B compliant TDR-94D (622-9210-501/-551)

For aircraft requiring ADS-B Out compliance in the United States or Europe, customers should utilize the -501 (fixed wing) and -551 (rotary wing) TDR-94D transponders.

For the TDR-94:

1. Purchase the DO-260B compliant TDR-94 622-9352-501/-551

For aircraft requiring ADS-B Out compliance in the United States or Europe, customers should utilize the -501 (fixed wing) and -551 (rotary wing) TDR-94 transponders.

2. Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

Contact your Rockwell Collins representative to inquire about last time purchases.

**Rockwell
Collins**

Building trust every day



How can we help?
Please call Rockwell Collins Customer Support at
+1.319.295.5000.

Building trust every day.

Rockwell Collins delivers innovative aviation and high-integrity solutions to commercial and government customers worldwide. Backed by a global network of service and support, we stand committed to putting technology and practical innovation to work for you whenever and wherever you need us. In this way, working together, we build trust. Every day.

For more information, contact:
Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
+1.319.295.4085
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com