



Special Notice

*****URGENT*****

Date: 15 April 2024
Subject: Incorrect Missed Approach Terminating Altitudes
Cycle 2403-2404

The following procedures were delivered with an incorrect altitude on the missed approach.

Airport	Procedures	Error
CYXE	ILS RWY 09 (L09)	The Localizer missed approach terminating altitude should be at or above 5000'.
CYZV	ILS RWY 09 (L09)	The Localizer missed approach terminating altitude should be at or above 3200'.

AeroNavData advises to use the procedures with extreme caution until an updated data delivery is made. The data will be updated to reflect the latest source in the cycle 2405 data effective Thursday, May 16, 2024.

Special notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. Information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to:

Email: production@aeronavdata.com

Fax: (314) 729-7006

9735 Landmark Pkwy, Suite 200
St. Louis, MO 63127