



!! URGENT !!

Date: 11 June 2024

Subject: Bangkok, Thailand
Suvarnabhumi Intl (VTBS)
ILS or LOC Z Rwy 19R
Cycle 2406

Procedure coding incorrect

Jeppesen NavData for cycle 2406, effective 13 June 2024, contains incorrect data for Suvarnabhumi Intl; Bangkok, Thailand (VTBS).

ILS or LOC Rwy 19R – waypoint **BS581** should read **fly-by**.

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2407, effective 11 July 2024. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
+1-303-328-4445 (Western Hemisphere)
+49 610 250 8175 (Eastern Hemisphere)
E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VTBS_2406