

Navigation Database Addendum

AIRAC 2501 – Issue 11

AIRAC AMDT MM 01/25 effective 23rd January 2025

AIRAC AMDT MM 08/24 effective 8th August 2024

MMSM Santa Lucia

Waypoint SM512

SIDs LORSU 2A RWY 04C, LORSU 2B RWY 04L, LORSU 1R RWY 22C and LORSU 1S RWY 22R

SID LORSU 2A and LORSU 2B:

- coordinates of WPT **SM512** should read **N19-42.7 W098-21.8** (N 19-42-40.5 W 098-21-45.4).

SID LORSU 1R RWY 22C and LORSU 1S RWY 22R are missing in DB.

Navdata will be updated effective AIRAC cycle 2502.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 15th January 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com