

Navigation Database Addendum

AIRAC 2501 – Issue 20

CY RCAP effective 26th December 2024

CYYF Penticton

APCH LOC A

Missed approach procedure:

Alt **7900ft** missing at AVTOP

Missed approach Holding length at AVTOP should read **1min**

Navdata will be updated effective AIRAC cycle 2502.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 22nd January 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com