

Navigation Special Notice

DATE: 09 January 2025

CYCLE: 2413 & 2501 Effective 26 DEC 2024 to 19 FEB 2025

SUBJECT: Incorrect Missed Approach Point

DESCRIPTION

The following procedure was delivered with an incorrect missed approach point:

Airport	Procedure	Error
KMCC	VOR/DME RWY 34	The missed approach point for this procedure is
	(D34)	at MCC 1.4 DME, not runway 34.

PILOT ACTION

Use the procedure with extreme caution

RESOLUTION

The data will be updated to reflect the latest source in the cycle 2502 data effective Thursday, February 20, 2025.

Special Notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. The information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to: Email: production@aeronavdata.com

Fax: (314) 729-7006

Garmin – St. Louis 9735 Landmark Pkwy, Suite 200 St. Louis, MO 63127