



**Collins
Aerospace**

05 June 2025

Cycle 2506-01

FORWARD TO CHIEF PILOT IMMEDIATELY

*****LPV Procedures Potentially Unusable*****

**To: All Jeppesen and LSY Navigation Data Operators
(Types 7, 8, 42/42C, 61/61C, 71)**
From: Aeronautical Data Services Technical Support
SUBJECT: Unusable LPV Procedures

OVERVIEW

LPV procedures have been determined to be unusable on at least one platform (A220) and may be unusable on other platforms. Collins is investigating the issue and will be communicating no later than 4:00 PM Central Time Friday, 6 June, 2025.

DETAIL

A processing issue within latest delivery of navigation data (2506) prevents the FMS from using LPV approaches properly on some aircraft. **Crews should not operate LPV procedures in 2506 databases until Collins provides further information.** We are urgently working to ensure LPV procedures are usable for cycle 2506 in all affected aircraft.

FUTURE

If you have questions regarding this Flight Alert, please contact Collins Aerospace, Aeronautical Data Services via email at CollinsDatabaseTech@Collins.com

WE URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE PERSONNEL