



06 June 2025

Cycle 2506-04

***FORWARD TO CHIEF PILOT IMMEDIATELY***

**\*\*\*LPV Procedures Unusable - Update\*\*\***

**To: All Jeppesen and LSY Navigation Database Operators  
(Types 42/42C, 61/61C, 71 Databases)**  
**From: Aeronautical Data Services Technical Support**  
**SUBJECT: REVISION A of Navigation Databases Released**

**OVERVIEW**

This is an update to the issues outlined in Flight Alert 2506-01 sent yesterday afternoon (05 June.) LPV procedures have been determined to be unusable on all ProLine Fusion and PL21 Advanced platforms using the database types mentioned above. In addition, for type 71 only, LP procedures have also been determined to be unusable. **Do not attempt to use these procedures with the data released on 04 June 2025**

**DETAIL**

A processing issue within the latest delivery of navigation data (2506) prevents the FMS from using LPV approaches properly in the mentioned database types. In addition, for type 71 only, this issue has had the same impact on LP procedures.

**A solution has been implemented and a revision to all affected databases is now available on the Collins Database Portal for immediate download. Collins recommends installing "Revision-A" of the navigation database prior to operating LPV approaches (in addition, LP approaches for Type 71 only)**

**FUTURE**

If you have questions regarding this Flight Alert, please contact Collins Aerospace, Aeronautical Data Services via email at [CollinsDatabaseTech@Collins.com](mailto:CollinsDatabaseTech@Collins.com)

***WE URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE PERSONNEL***