



# **JEPPESEN®**

## **NavData® Alert**

### **!! URGENT !!**

**Date:** 06 June 2025

**Subject:** Tindal, Northern Territory, Australia  
Tindal (YPTN)  
TACAN Rwy 14L  
Cycles 2505/2506

***Procedure information outdated***

Jeppesen NavData for cycle 2505, effective 15 May 2025, and for cycle 2506, effective 12 June 2025 contains incorrect data for Tindal, Northern Territory, Australia (YPTN). NOTAM C0248/25 (eff 01 JUN 25) was received after the ICAO specified date for aeronautical information publication.

**TACAN Rwy 14L** procedure is missing from the database.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO  
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2507, effective 10 July 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

**Support Portal:** [support.jeppesen.com](https://support.jeppesen.com)

**E-mail:** [navdatasupport@boeing.com](mailto:navdatasupport@boeing.com)

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

YPTN\_2505/2506