



## Navigation Database Addendum

### **AIRAC 2506 – Issue 3**

**AIRAC AMDT 182/25 effective 20th March 2025**

### **YPDN Darwin Intl**

---

#### **Runway 11/29**

Temporary threshold displacements are not coded in FMS database.

- Coordinates displaced threshold RWY 11: S12-24-42.51 E130-52-20.75
- Coordinates displaced threshold RWY 29: S12-24-59.89 E130-53-12.37

Temporary approach procedures established:

- NDB11-T, RNP11-T, VOR11-T
- LOC29-T, RNP29-T, VOR29-T

Approach profiles for the established temporary procedures are adjusted to lead to the displaced threshold.

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Friday, 23<sup>rd</sup> May 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)