



JEPPESSEN®

NavData® Alert

!! URGENT !!

Date: 25 July 2025

Subject: Tuticorin, India
Tuticorin (VOTK)
Multiple procedures
Cycle 2507 & 2508

Procedure information outdated

Jeppesen NavData for cycle 2507, effective 10 July 2025, and for cycle 2508, effective 07 August 2025 contains incorrect data for Tuticorin, India (VOTK). India AIP Supplements 133/25, 134/25 and 135/25, initially effective 4 September 2025, were preponed by NOTAM C0418/25 (published 23 JUL 25) to be **already effective 23 July 2025**. All Supplements listed contain revised runway and procedures information, which could therefore not be incorporated in time.

Procedures **VOR Rwy 10**, **VOR Rwy 28** and **NDB Rwy 28** are completely revised, therefore should not be used.

**WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO
APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!**

Revised coding will appear in Jeppesen NavData for cycle 2509, effective 04 September 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: [Notices and Alerts](#).

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:
Support Portal: digitalsuccess.jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.

VOTK_2507_2508