

Navigation Special Notice

DATE: 28 August 2025

CYCLE: 2508 Effective 07 AUG 2025 to 04 SEP 2025

SUBJECT: Incorrect flight path

DESCRIPTION

Garmin has been made aware that the following procedure was delivered with an incorrect departure route:

Airport	Procedure	Error
КМСО	FSHUN4 DEPARTURE	Runways 17L/R and 18L/R have an incorrect flight path. The vectors after BAAIT should proceed directly to FSHUN.

PILOT ACTION

Do not use runways 17L/R and 18L/R in any manner.

RESOLUTION

The data will be updated to reflect the latest source in the cycle 2509 data effective Thursday, September 04, 2025.

Special Notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. The information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to: Email: production@aeronavdata.com

Fax: (314) 729-7006

Garmin – St. Louis 9735 Landmark Pkwy, Suite 200 St. Louis, MO 63127