



GARMIN®

Navigation Special Notice

DATE: 10 September 2025
CYCLE: 2509 Effective 04 SEP 2025 to 02 OCT 2025
SUBJECT: Incorrect Missed Approach Route

DESCRIPTION

The following procedure was delivered with an incorrect missed approach route:

Airport	Procedure	Error
PABI	NDB-A	The NDB-A procedure contains an incorrect missed approach route. The missed approach should be a climbing right turn to 5300 on DJN brg 012° before returning to DJN and holding.

PILOT ACTION

Use caution when flying the missed approach in cycle 2509.

RESOLUTION

The data will be updated to reflect the latest source in the cycle 2510 data effective Thursday, October 02, 2025.

Special Notices are disseminated to notify customers of issues with navigational data which may affect flight operations or safety. The information contained herein should be immediately relayed to appropriate personnel!

Important: Check NOTAMs and other pertinent information prior to flight.

All questions regarding this Special Notice should be addressed to:
Email: production@aeronavdata.com
Fax: (314) 729-7006

Garmin – St. Louis
9735 Landmark Pkwy, Suite 200
St. Louis, MO 63127