

# Airshow® DVD Player Discontinuance

Ref. No. 2006-039M

Pub Date 09/2006

Due to the need for technology advancement and obsolescence of key hardware components, Rockwell Collins will stop taking orders for the DVD players identified in this bulletin. This discontinuance is effective immediately. Orders that have already been placed with Rockwell Collins as of the publication of this bulletin will be fulfilled. Deliveries to meet OEM requirements will continue as planned individually with each OEM.

Rockwell Collins will continue to provide rental exchange units, repairs and product support for these products through December 2008.



Part Number	Description
3300-1-1	DVD Player
3300-1-2	DVD Player
3300-1-21	DVD Player Flush Mount 7.5"
3300-1-22	DVD Player Rack Mount 8.5"
3300-1-23	DVD Player Flush Mount 11.5"
3300-1-24	DVD Player Rack Mount 12.5"
3300-1-3	DVD Player
3300-1-4	DVD Player
3310-1-1	DVD Player Flush Mount 7.5" – 1394 Direct
3310-1-2	DVD Player Rack Mount 7.5" – 1394 Direct
3301-1-1	DVD Player
3301-1-2	DVD Player Rack Mount 8.5"
3301-1-3	DVD Player Flush Mount 11.5"
3301-1-4	DVD Player Rack Mount 12.5"
3302-1-1	DVD Player
3302-1-2	DVD Player Rack Mount 8.5"
3302-1-3	DVD Player Flush Mount 11.5"
3302-1-4	DVD Player Rack Mount 12.5"

## NEW DUAL DISK MULTI-REGION DVD PLAYER

Rockwell Collins will offer a new dual disk multi-region DVD player, ADVD-6220, part number 866-0027-002 or -004, as a replacement for the discontinued DVD players affected by this bulletin. In addition to providing two disk drives in one unit, the ADVD-6220 also provides other enhanced features compared to the discontinued players:

- CD Media: CD-DA, CD-ROM, Enhanced Music CD, CD Extra, CD Plus, MP3 from CD-R, CD-RW and Multi-session CDs
- DVD Media: DVD single and dual layer (PTP, OTP), DVD-R, DVD+R, DVD-RW, DVD+RW
- Accepts DVDs from all Regions and Region Code Enhanced DVDs
- Ability to integrate DVD Title, and CD Play lists with Rockwell Collins CMS via the MDSB bus (corresponding software changes are required in the Rockwell Collins CMS to enable these features)
- Coaxial and Toslink SPDIF interfaces

The new ADVD-6220 DVD player will be available in both rack mount and flush mount configurations. The dimensions of the ADVD-6220, part number 866-0027-002 (rack mount) are 3.21 in. (h) by 8.50 in. (w) by 9.86 in. (d) and for part number 822-0027-004 (flush mount) are 3.21 in. (h) by 7.50 in. (w) by 9.86 in. (d).

Special Note: Some applications may require a system software update, a hardware addition and other possible installation considerations. It is recommended that customers work with their Rockwell Collins Customer Support representative to evaluate installation compatibility for their specific application.

How can we help?

Please call Rockwell Collins Customer Support at 319.295.5000.

Building trust every day.

Rockwell Collins delivers smart communication and aviation electronic solutions to customers worldwide. Backed by a global network of service and support, we stand committed to putting technology and practical innovation to work for you whenever and wherever you need us. In this way, working together, we build trust. Every day.

For more information, contact:

Rockwell Collins  
400 Collins Road NE  
Cedar Rapids, Iowa 52498  
+1.319.295.4085  
email: [csmarketing@rockwellcollins.com](mailto:csmarketing@rockwellcollins.com)  
[www.rockwellcollins.com](http://www.rockwellcollins.com)

**Rockwell  
Collins**

Building trust every day