

Air Speed Indicator (ASI) 850, 850(A) Production Discontinuance

Ref. No. 2014-128M

Pub Date 09/2014

At Rockwell Collins, we appreciate your selection of our products for your aircraft, and strive to provide you with the best quality parts and service. Occasionally, advancements in the technologies we offer our customers or the availability of parts and components, necessitate that we cease production and phase out the support of older solutions. This is the case with the Air Speed Indicator (ASI) 850, 850(A).

PRODUCTION DISCONTINUANCE

Effective September 1, 2014, Rockwell Collins is announcing the discontinuance of production of the ASI-850 and ASI-850(A). Rockwell Collins will continue to provide repair services for these products on a parts available basis.

AIR SPEED INDICATOR – DISCONTINUED PART NUMBER

Equipment Type	Discontinued Part Number
ASI-850	622-7204-xxx
ASI-850(A)	622-8335-xxx

To help ensure maximum operation of the aircraft, Rockwell Collins is encouraging our customers to be proactive in planning for the discontinuance.

For assistance in determining the proper replacement, please contact your Rockwell Collins Authorized Dealer or Rockwell Collins Regional Sales Manager/ Customer Support Engineer (CSE) for more information.

How can we help?

Please call Rockwell Collins Customer Support at +1.319.295.5000.

For more information, contact:

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
+1.319.295.4085
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day