

Electronic Flight Display (EFD) 4077 and 4077(A) Production Discontinuance

Ref. No. 2014-129M

Pub Date 11/2015

At Rockwell Collins, we appreciate your selection of our products for your aircraft, and strive to provide you with the best quality parts and service. Occasionally, advancements in the technologies we offer our customers or the availability of parts and components, necessitate that we cease production and phase out the support of older solutions. This is the case with the Electronic Flight Display (EFD) 4077 and 4077(A).

Effective September 1, 2014, Rockwell Collins is announcing the discontinuance of production on the Cathode Ray Tube (CRT) based Electronic Flight Display (EFD), specifically the EFD-4077 and EFD-4077(A). Rockwell Collins will continue to provide repair services for these products on a parts available basis.

ELECTRONIC FLIGHT DISPLAY– LAST TIME BUY PRODUCTION

Last time buy orders will be accepted until December 1, 2014, or until available components are consumed. All deliveries must be taken on or before December 1, 2015.

Equipment Type	Last Time Buy Part Number
EFD-4077	622-9978-110, -114, -122, -126, 310, -314, -402, -404, -406, -408

For additional information in planning your upgrades, please contact your Rockwell Collins Regional Sales Manager or Rockwell Collins Customer Support Engineer.

ELECTRONIC FLIGHT DISPLAY– DISCONTINUED PRODUCTION

Equipment Type	Discontinued Part Number
EFD-4077	622-9978-001, -002, -020, -022, -024, -026, -028, -101, -102, -104, -106, -108, -112, -116, -118, -120, -124, -128, -130, -201, -202, -301, -302, -304, -306, -308, -312
EFD-4077(A)	822-0322-xxx

To help ensure maximum operation of the aircraft, Rockwell Collins is encouraging our customers to be proactive in planning for the discontinuance. Our recommended replacement solution is to upgrade your aircraft with our Pro Line 21 LCD flight deck display.

For Supplemental Type Certificate (STC) information reference the table below:

Aircraft Make/Model	Replacement Solution	STC Information
Dassault Falcon F-2000/2000EX	Pro Line 4 to 21 with IFIS-5000	Rockwell Collins STC ST11047SC
Dassault Falcon F-50EX	Pro Line 4 to 21 with IFIS-5000	Rockwell Collins STC ST11041SC

For assistance in determining the proper replacement, please contact your Rockwell Collins Authorized Dealer or Rockwell Collins Regional Sales Manager/ Customer Support Engineer (CSE) for more information.

How can we help?
Please call Rockwell Collins Customer
Support at +1.319.295.5000.

For more information, contact:

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
+1.319.295.4085
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com