2016-142M Pub. Date: 02/2016

## **Production and Support Discontinuance Bulletin**

Legacy Airshow 400/410 Moving Map Systems

### **Summary**

Due to the obsolescence of key hardware components and the need for technology advancement, Rockwell Collins has discontinued support of several legacy Airshow Moving Map products.

#### Am I affected?

Effective immediately the parts listed on this notice will no longer be supported by Rockwell Collins. Rockwell Collins will make its best efforts to service these legacy Airshow parts, including repairs and software customizations, for as long as possible. Customers are advised that availability of select parts is limited, which can create extended repair turnaround times and in some cases prevent units from being repaired.

| Product type        | Description                          | Obsolete part number | Replacement product    |
|---------------------|--------------------------------------|----------------------|------------------------|
| Airshow 400         | Flange Mount                         | 920040               | AS4000 or AS500        |
| Airshow 400         | 1/2-ATR, NTSC Composite Video        | 920050               | AS4000 or AS500        |
| Airshow 400         | 1/2-ATR, RGB Video                   | 920052               | AS4000 or AS500        |
| Airshow 400         | 1/2-ATR, Y/C Video                   | 920053               | AS4000 or AS500        |
| Airshow Genesys     | 1/2 ATR, Dual Channel NTSC           | 920060               | AS4000 or AS500        |
| Airshow Genesys     | 1/2 ATR, NTSC and RGB                | 920062               | AS4000 or AS500        |
| Airshow Genesys     | Flange Mount, Dual channel NTSC      | 920070               | AS4000 or AS500        |
| Airshow Genesys     | Flange Mount, NTSC and RGB           | 920072               | AS4000 or AS500        |
| Airshow Genesys     | Remote CD ROM drive                  | 920080               | AS4000 or AS500        |
| Airshow Genesys     | Flange Mount, NTSC, external CD      | 920090               | AS4000 or AS500        |
| Airshow Genesys     | Flange Mount, NTSC/RGB , external CD | 920092               | AS4000 or AS500        |
| Airshow 410         | Digital Interface Unit               | 920055               | AS4000 or AS500        |
| Time to Destination | Time to Destination Controller       | 911010-1             | Flight Deck Controller |
| Time to Destination | Time to Destination Controller       | 911010-2             | Flight Deck Controller |

## What are my options?

Rockwell Collins has developed replacement products for these discontinued items. See the table for the affected parts and recommended replacement product. Rockwell Collins offers trade-in discounts for customers that wish to upgrade to a new Airshow product. Please consult with your Rockwell Collins Regional Sales Manager to determine what discounts are available for each product.

#### Upgrade to these new products

- > Airshow 4000 (PN 925000-100)
- > Airshow 500 Tray Mount (PN 441-1333-100)
- > Airshow 500 Flange Mount (PN 441-1332-100)
- > Flight Deck Controller (922000-1, 922000-2, 922000-3)

Please contact your Rockwell Collins Regional Sales Manager to discuss options and for commercial and lead time information.



# For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins 400 Collins Road NE Cedar Rapids, Iowa 52498 319.295.4085

fax: 319.295.2297

email: csmarketing@rockwellcollins.com

www.rockwellcollins.com

