

Production Discontinuance Bulletin

Navigation Radio Altimeter ALI-55/55A, ALT-50A, RAC-870

Summary

Rockwell Collins will discontinue production deliveries of the Altimeter Indicator ALI-55/55A, ALT-50A, and Converter RAC-870 due to obsolescence of a key component.

We will continue to provide the service and support you have come to expect from Rockwell Collins on a parts available basis. Additionally, Rockwell Collins may still be able to offer assistance in troubleshooting and repairing this product.

Am I affected?

The following parts will discontinue production starting on the date below.

Product	Part number	Replacement Type	Replacement P/N
ALI-55	622-2937-001	No Replacement	No Replacement
ALI-55	622-2937-002	No Replacement	No Replacement
ALI-55	622-2937-003	No Replacement	No Replacement
ALI-55	622-2937-004	No Replacement	No Replacement
ALI-55	622-2937-005	No Replacement	No Replacement
ALI-55	622-2937-008	No Replacement	No Replacement
ALI-55	622-2937-009	No Replacement	No Replacement
ALI-55A	622-2938-001	No Replacement	No Replacement
ALI-55A	622-2938-002	No Replacement	No Replacement
ALI-55A	622-2938-003	No Replacement	No Replacement
ALI-55A	622-2938-004	No Replacement	No Replacement
ALT-50A	622-3201-001	ALT-1000	822-1939-XXX
ALT-50A	622-3201-002	ALT-1000	822-1939-XXX
ALT-50A	622-3201-011	ALT-1000	822-1939-XXX
ALT-50A	622-3201-012	ALT-1000	822-1939-XXX
RAC-870	622-7209-001	RAC-870	622-7209-005
RAC-870	622-7209-002	RAC-870	622-7209-005
RAC-870	622-7209-003	RAC-870	622-7209-005
RAC-870	622-7209-004	RAC-870	622-7209-005

Rockwell Collins will still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

Upgrade to an ALT-1000 with RAC-870 (-005)

New purchase orders created after January 1, 2016, should be converted to the Rockwell Collins Altimeter ALT-1000/4000 with the RAC-870 (-005) converter.

The Rockwell Collins ALT-1000 provides the highly reliable and accurate height information you need for each landing approach. With exclusive digital processing techniques, full end-to-end monitoring and critical-level software verification, the ALT-4000 supports Category III automatic landing systems when installed in a dual or triple configuration and Category II aircraft certifications using a single radio altimeter.

Easily upgrade to an ALT-1000 or from a Rockwell Collins ALT-50A radio by installing the available direct plug-and-replace versions.

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
319.295.4085
fax: 319.295.2297
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day