

Guaranteed Repair Discontinuance Bulletin

Navigation ADF Sense Coupler ACA-80

Summary

Rockwell Collins will discontinue Support of the ADF Sense Coupler ACA-80 due to obsolescence of a key component.

We will continue to provide the service and support you have come to expect from Rockwell Collins on a parts available basis. Additionally, Rockwell Collins may still be able to offer assistance in troubleshooting and repairing this product.

Am I affected?

The following parts will discontinue support.

Product	Part number	Replacement Type	Replacement P/N
ACA-80	622-5691-001	No Replacement	No Replacement
ACA-80	622-5691-002	No Replacement	No Replacement
ACA-80	622-5691-003	No Replacement	No Replacement
ACA-80	622-5691-004	No Replacement	No Replacement

Rockwell Collins will still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins
 400 Collins Road NE
 Cedar Rapids, Iowa 52498
 319.295.4085
 fax: 319.295.2297
 email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day