

Guaranteed Repair Discontinuance Bulletin

Navigation Radio Altimeter ALI-55B, ANT-50, ANT-51, DRI-55, RAC-875

Summary

Rockwell Collins will discontinue support of the Altimeter Indicator ALI-55B, Antenna ANT-50/ANT-51/437X-1B, Digital Radio Altitude Indicator DRI-55, and the Radio Altitude Converter RAC-875 due to obsolescence of a key component.

We will continue to provide the service and support you have come to expect from Rockwell Collins on a parts available basis. Additionally Rockwell Collins may still be able to offer assistance in troubleshooting and repairing this product.

Am I affected?

The following parts will discontinue support.

Product	Part number	Replacement Type	Replacement P/N
437X-1B	622-0954-001	No Replacement	No Replacement
437X-1B	622-0954-002	No Replacement	No Replacement
ALI-55B	622-5367-001	No Replacement	No Replacement
ANT-50A	622-3698-001	No Replacement	No Replacement
ANT-50A	622-3698-001	No Replacement	No Replacement
ANT-51A	622-4550-001	No Replacement	No Replacement
DRI-55	622-4160-001	No Replacement	No Replacement
DRI-55	622-4160-002	No Replacement	No Replacement
DRI-55	622-4160-003	No Replacement	No Replacement
DRI-55	622-4160-004	No Replacement	No Replacement
DRI-55	622-4160-005	No Replacement	No Replacement
DRI-55	622-4160-006	No Replacement	No Replacement
DRI-55	622-4160-007	No Replacement	No Replacement
DRI-55	622-4160-008	No Replacement	No Replacement
DRI-55	622-4160-011	No Replacement	No Replacement
DRI-55	622-4160-012	No Replacement	No Replacement
DRI-55	622-4160-013	No Replacement	No Replacement
DRI-55	622-4160-014	No Replacement	No Replacement
DRI-55	622-4160-015	No Replacement	No Replacement
DRI-55	622-4160-016	No Replacement	No Replacement
DRI-55	622-4160-017	No Replacement	No Replacement
DRI-55	622-4160-018	No Replacement	No Replacement
RAC-875	822-0778-001	No Replacement	No Replacement
RAC-875	822-0778-002	No Replacement	No Replacement
RAC-875	822-0778-003	No Replacement	No Replacement

Rockwell Collins will still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
319.295.4085
fax: 319.295.2297
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day