

Production Discontinuance Bulletin

Navigation Receivers VIR-32, VIR-33

Summary

Effective February 24, 2017, Rockwell Collins will discontinue production deliveries of the Navigation Receivers VIR-32 and VIR-33 due to obsolescence of a key component.

We will continue to provide the service and support you have come to expect from Rockwell Collins on a parts available basis. Additionally, Rockwell Collins may still be able to offer assistance in troubleshooting and repairing this product.

Am I affected?

The following parts will discontinue production.

Product	Part number	Replacement Type	Replacement P/N
VIR-32	622-6137-XXX	VIR-4000	822-1467-001
VIR-33	822-0400-001	VIR-4000	822-1467-001

Rockwell Collins will maintain a suitable balance of the obsolete non-procurable parts to continue to provide field support of the existing VIR units. Rockwell Collins will continue to provide the service and support you have come to expect, however, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product when parts become unavailable. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

Participate in our Last Time Buy

Orders for the existing VIR-32 or VIR-33 must be placed by January 20, 2017, with orders requested by February 24, 2017.

Upgrade to VIR-4000 Navigation Receiver

The VIR-4000 integrated Navigation Receiver is a fully digital device for use with Rockwell Collins Pro Line generations of avionics. The devices offer a variety of installation options. They are controlled by either an ARINC 429 signal or by a CTL-32G. With a CTL-32G, the radio's self-diagnostic tests are enabled by the self-test button and displayed on the control.

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
319.295.4085
fax: 319.295.2297
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day