

ADF-462 AND VIR-432

## SUMMARY

Effective 01 May 2021, Collins Aerospace will no longer accept orders for the ADF-462 and the VIR-432 due to obsolescence of key components. We offer a last time buy opportunity as described in the *What are my options?* section.

The ADF-4000 and VIR-4000 are readily available as FUNCTIONAL replacements to the ADF-462 and the VIR-432, respectively. See more details in the *Upgrade to an ADF-4000 and VIR-4000* section.

## AM I AFFECTED?

This production discontinuance is related to the specific parts / part families listed below.

Product Type	Part number
ADF-462	622-7382-XXX
VIR-432	622-7194-XXX

Collins Aerospace will continue to provide the service and support for these products that you have come to expect. This includes:

- Repair of units by our Service Centers
- Continuation of Technical Support
- Engineering Support
- Drawing and Manual Updates
- Service Bulletins if necessary

Additionally, Collins Aerospace can provide assistance exploring the transition to the ADF-4000 and or VIR-4000, where necessary.

## WHAT ARE MY OPTIONS?

### Participate in our Last Time Buy

For customers interested in maintaining ADF-462 and VIR-432 within their fleets, Collins Aerospace has several options to help.

Customers interested in participating in a Last Time Buy should submit a purchase order by 01 May 2021 with delivery by 01 May 2022. Limited production inventory is available and Collins Aerospace can only guarantee deliveries while supplies last.

### Upgrade to a ADF-4000 or VIR-4000

For customers seeking a highly capable solution to this discontinuance, the Collins Aerospace ADF-4000 (CPN 822-1470-001) and VIR-4000 (CPN 822-1467-001) are readily available.

The ADF-4000 and VIR-4000 gives your aircraft:

- Digital Audio Outputs
- Field Loadable Software
- Improved Reliability
- Reduced Equipment Size and Weight
- Utilization of existing antennas

Installation and mount kit changes will be necessary to implement the ADF-4000 and/or VIR-4000. Collins is available to provide support as necessary to install and certify the ADF-4000 and/or VIR-4000 in your aircraft.

For more information, please contact Collins Aerospace Marketing at [csmarketing@collins.com](mailto:csmarketing@collins.com).

### Contact Intertrade for used equipment

Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Collins Intertrade at 1.319.378.3500,

[intertradesales@rockwellcollins.com](mailto:intertradesales@rockwellcollins.com), or on the web at

[https://www3.rockwellcollins.com/intertrade/..](https://www3.rockwellcollins.com/intertrade/)



**Collins Aerospace**

+1.319.295.5000 | +1.319.295.4085

[avionicsmarketing@collins.com](mailto:avionicsmarketing@collins.com)

[collinsaerospace.com](http://collinsaerospace.com)