

## Performance Software Type 1 LOA AMDB Product

2095 W. Pinnacle Peak Rd. Suite 120 Phoenix, Arizona 85027 623.780.1517 Fax: 623.580.4873

www.psware.com

Airport Mapping Database – <i>Flight Alert</i>		
PSW Issue Number	FA-024-0009	TJI
Affected Database Cycle	2407 - 2409	stands located on it, or the taxiways connecting it to taxiway E.
Affected Airport	LFPG	
Detailed Description	The Airport Mapping Database for LFPG does not contain the Northern part of Apron J, the parking stands located on it, or the taxiways connecting it to taxiway E.	
Pilot Actions	Be aware, the Airport Mapping Database for LFPG does not contain the Northern part of Apron J, the parking stands located on it, or the taxiways connecting it to taxiway E.  When navigating on the Northern part of Apron J, it is recommended to use the AIP.	
Corrective Action	This AMM is in the process of being updated to include the Northern part of Apron J, the parking stands located on it, and the taxiways connecting it to taxiway E.	
Anticipated Correction Cycle	2409	