

Performance Software Type 1 LOA AMDB Product

2095 W. Pinnacle Peak Rd. Suite 120 Phoenix, Arizona 85027

623.780.1517 Fax: 623.580.4873 www.psware.com

Airport Mapping Database - Flight Alert PSW Issue Number FA-024-0004 Affected Database 2304 - 2405Cycle Affected Airport LIBR The Airport Mapping Database currently does not Detailed include the updated parking Description stands near the Terminal Building. Be aware, the Airport Mapping Database currently does not include the updated parking stands near the Terminal Building. Pilot Actions When parking near the Terminal Building, it is recommended to use the AIP and follow directions according to ATC. This AMM is in the process TERMINAL BUILIDING of being updated to include the updated parking stands Corrective Action near the Terminal Building. Anticipated 2405 Correction Cycle The Airport Mapping Database currently does not include the updated parking stands near the Terminal Building.



Performance Software Type 1 LOA AMDB Product

2095 W. Pinnacle Peak Rd. Suite 120 Phoenix, Arizona 85027 623.780.1517 Fax: 623.580.4873

www.psware.com

623.780.1517 Performance Software www.psware.com