

## Navigation Database Addendum

### AIRAC 2406 – Issue 8

SUP S04/24 effective 22nd February 2024

### LIBP Pescara

---

#### Runway 04/22

From 22 February 2024 runway extension works will take place.  
Works are divided into four phases that will be activated by Notam.

##### Phases 1, 2, 3:

- RWY length 2214 (m)
- Coordinates THR RWY 04 N42 25 26.59 / E014 10 31.81
- THR Elevation RWY 04 45.3ft
- Aerodrome Elevation 45ft
- Take off RWY 22, landing RWY 04 and intersection take off B forbidden
- ILS not available
- SIDs RWY 22 suspended
- Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW04	2214	2214	2214	not available
Intersection take off C	1625	1625	1625	not available

	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW22	not available	not available	not available	2026

##### Phase 4:

- ILS/DME RWY 22 operating with new ident IPSC
- New localizer antenna position N42 25 08.9 E014 10 13.5

Please disseminate this information to all affected crews

Lufthansa Systems  
FMS Customer Support  
Tuesday, 11<sup>th</sup> June 2024

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>  
For any inquiries, please contact [fms.support@lhsystems.com](mailto:fms.support@lhsystems.com)