



16 July 2024

Cycle 2407-01

FORWARD TO CHIEF PILOT IMMEDIATELY

***** J61/J71 World and EurAsiaPac Navigation Databases – ZBHH & UDYZ SIDs*****

To: Operators using J61/J71 World and EAP Nav databases.
From: Aeronautical Data Services Technical Support
SUBJECT: 2407 ZBHH and UDYZ SIDs Unusable

OVERVIEW

Several Standard Instrument Departure (SID) procedures at ZBHH and UDYZ were included in the 2407 J61 EAP and World and J71 World navigation databases that are not compatible with the Fusion FMS.

DETAIL

An unexpected processing issue caused previously excluded SIDs at ZBHH and UDYZ to be included. This issue only affects the following database types and coverage regions:

- **J61 Europe Asia Pacific**
- **J61 Africa Asia Australia**
- **J61 World**
- **J71 World**

The following SIDs are included in these navigation databases and **should not** be used:

| Area Code | Airport Ident | Airport ICAO | Procedure Ident |
|-----------|---------------|--------------|-----------------|
| EEU | UDYZ | UD | SEVA3H |
| EEU | ZBHH | ZB | DUD01D |
| EEU | ZBHH | ZB | IBA01D |
| EEU | ZBHH | ZB | TOD01D |
| EEU | ZBHH | ZB | TUS01D |
| EEU | ZBHH | ZB | DUD12D |
| EEU | ZBHH | ZB | IBA11D |
| EEU | ZBHH | ZB | LUG11D |
| EEU | ZBHH | ZB | TOD11D |
| EEU | ZBHH | ZB | TUS11D |

Using these SIDs could create a flight condition in which the FMS Flight Director indicates a turn in the opposite direction to the charted path.

FUTURE

This situation will be remedied in the Cycle 2408 navigation databases, to be delivered in the coming weeks.

If you have questions regarding this Flight Alert, please contact Collins Aerospace, Aeronautical Data Services via email at CollinsDatabaseTech@Collins.com

WE URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE PERSONNEL