

## !! URGENT!!

Date: 4 January 2025

Subject: Windhoek, Namibia

Hosea Kutako Intl (FYWH)

UTULO 1A [UTUL1A] RNAV Departure (Rwy 08), UTULO 1B [UTUL1B] RNAV Departure (Rwy 26)

**Cycle 2413** 

Incorrect procedure titles.

Jeppesen NavData for cycle 2413, effective 26 December 2024, contains the incorrect procedure titles for UTULO 1A [UTUL1A] RNAV Departure and UTULO 1B [UTUL1B] RNAV Departure.

The correct procedure titles should be UVORI 1A [UVOR1A] for Rwy 08 and UVORI 1B [UVOR1B] for Rwy 26.

## WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2501 effective 23 January 2025. Until then an entry will appear in the NavData Change Notices, and this Alert will be posted on the Jeppesen Web site: Notices and Alerts.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Support Portal: <a href="mailto:support.jeppesen.com">support.jeppesen.com</a>
E-mail: <a href="mailto:navdatasupport@boeing.com">navdatasupport@boeing.com</a>

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.