



Navigation Database Addendum

AIRAC 2501 – Issue 17

SUP LI S41/24 effective 26th December 2024

LIBP Pescara

Runway 04/22

From 26 December 2024 runway extension works will take place.
Works are divided into four phases that will be activated by Notam.

Phases 1, 2, 3:

RWY length 2214 (m)

Coordinates THR RWY 04 N42 25 26.59 / E014 10 31.81

THR Elevation RWY 04 45.3ft

Aerodrome Elevation 45ft

Take off RWY 22, landing RWY 04 and intersection take off B forbidden.

ILS not available

SIDs RWY 22 suspended

Procedures ILS Z RWY 22, ILS Y RWY 22, LOC Z RWY 22 and LOC Y RWY 22 are suspended

	TORA (m)	TODA (m)	ASDA (m)	LDA (m)
RW04	2214	2214	2214	not available
Intersection take off C	1625	1625	1625	not available

	TORA (m)	TODA(m)	ASDA(m)	LDA (m)
RW22	not available	not available	not available	2026

Phase 4:

ILS/DME RWY 22 operating with new ident IPSC

New localizer antenna position **N42-25-08.9 E014-10-13.5**

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 21st January 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com