

Navigation Database Addendum

AIRAC 2504 – Issue 11

SUP SC VOL II 03/25 effective 17th April 2025

NOTAM SC A0819/25 effective 17th April 2025

NOTAM SC A1068/25 effective 14th April 2025

NOTAM SC A1067/25 effective 1st May 2025

NOTAM SC A1069/25 effective 14th April 2025

SCAR Arica Chacalluta

Runway RWY 02/20 and PROCs

RWY 02/20 and related procedures are missing in the database.

- RWY 02 THR: S18-21.5 W070-20.5 (S18-21-28.17 W070-20-31.71)
- RWY 20 THR: S18-20.4 W070-20.1 (S18-20-21.24 W070-20-07.18)

SIDs RWY 20:

- AZAPA 3, ERISO 3J, LOBAG 3K, LOBAG 3R, LOBAG 4L, LOLES 2, PUGOT 3R, PUGOT 4B, VAGUR 3

STARs RWY 02:

- ERISO 4A, SIRAM 1A, SIRAM 2B, VAGUR 4B

APCHs:

- VOR Z RWY 02, VOR Y RWY 02, RNP RWY 02 (LNAV only)

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Tuesday, 15th April 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com