

!! URGENT !!

Date: 04 June 2025

Subject: Bintulu, Malaysia Bintulu (WBGB) RNP Y RWY 17 Cycle 2506

Procedure information incorrect

Jeppesen NavData for cycle 2506, effective 12 June 2025 contains incorrect data for Bintulu, Malysia (WBGB).

RNP Y RWY 17:

- waypoint **GB503** should read **GB510**
- waypoint **KASPA hold entry** should be **fly by**

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

Revised coding will appear in Jeppesen NavData for cycle 2507, effective 10 July 2025. Until then an entry will appear in the NavData Change Notices and this Alert will be posted on the Jeppesen Web site: <u>Notices</u> <u>and Alerts</u>. Please refer to chart Bintulu, Malaysia (WBGB) 12-1 dated 6 JUN 25 (effective 12 June 25) for valid information.

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at: Support Portal: support Portal: support.jeppesen.com E-mail: navdatasupport@boeing.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. End NavData users should consult with their Avionics Provider for definitive information on whether their system is affected by this Alert.