

Navigation Database Addendum

AIRAC 2506 – Issue 13

SUP 04/2024 effective 25th January 2024

FZIC Kisangani Bangoka Intl

Runway 12

RWY 12 temporarily displaced by 750m.

Coded APCHs do not lead to the landing threshold, vertical guidance should not be used.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Wednesday, 11th June 2025

All valid FSAs/NDAs are available on <u>http://fms-info.lhsystems.com</u> For any inquiries, please contact <u>fms.support@lhsystems.com</u>