

Navigation Database Addendum

AIRAC 2506 – Issue 19 LT AIRAC AMDT 06/25 effective 12th June 2025

LTFM Istanbul

APCH RNP 35R Z

Missed approach holding at GITVO should read 048° inbound, left turn.

Navdata will be updated effective AIRAC cycle 2508.

Please disseminate this information to all affected crews

Lufthansa Systems FMS Customer Support Tuesday, 1st July 2025

All valid FSAs/NDAs are available on http://fms-info.lhsystems.com
For any inquiries, please contact fms.support@lhsystems.com