

Navigation Database Addendum

AIRAC 2506 – Issue 7

NOTAM A2304/25 effective 3rd June 2025

SANU San Juan Domingo F.Sarmiento

APCH VOR Z RWY 18

Due to late receipt of NOTAM, VOR Z RWY 18 is missing in the DB.

Navdata will be updated effective AIRAC cycle 2507.

Please disseminate this information to all affected crews

Lufthansa Systems
FMS Customer Support
Wednesday, 04th June 2025

All valid FSAs/NDAs are available on <http://fms-info.lhsystems.com>
For any inquiries, please contact fms.support@lhsystems.com