

中国民用航空总局

GENERAL ADMINISTRATION OF CIVIL AVIATION OF CHINA

维修许可证申请书

APPLICATION FOR ISSUE OF MAINTENANCE ORGANIZATION CERTIFICATE

1. 申请单位名称/Name of applicant Rockwell Collins, Inc.

2. 单位通讯地址/Address 32125 32nd Ave So Suite 110
Federal Way, Washington 98001 U.S.A.

3. 电话/Telephone 253-733-3700 传真/Fax 253-733-3705

4. 申请理由/Reason for application

- (1) 初次申请/Original application for certificate
 (2) 改变维修类别或项目/Change in maintenance rating or items
 (3) 改变地点或设施/Change in location or facilities of organization
 (4) 改变机构或名称/Change in organization structure or name
 (5) 其它/Others / MOM update

5. 申请的维修项目/Maintenance functions applied for

- | | |
|---|--|
| <input type="checkbox"/> 机体/Airframe | <input type="checkbox"/> 动力装置/Powerplant |
| <input type="checkbox"/> 螺旋桨/Propeller | <input checked="" type="checkbox"/> 航空器部件/Components |
| <input type="checkbox"/> 特种作业/Specialized service | <input checked="" type="checkbox"/> 其它/Others /MOM |

6. 责任经理/Accountable Manager

姓名/Name Scott Losos 职务/Title Service Center Manager

签名/Signature  日期/Date 13 June 2017

7. 具体申请维修项目及地点/Detail maintenance functions applied for and facilities location

Inspection; test; repair; and modification of Rockwell Collins equipment at the Federal Way, Washington U.S.A. facility.

Additional Component part numbers are as follows:

822-3253-101	DPC-2120 Display Processing Computer	ATA 31-41-92
822-3252-101	DCP-2120 Display Control Panel	ATA 31-41-93
822-3250-101	AFD-212- Adaptive Flight Display	ATA 31-61-14
822-2911-021	TTR-2100 TCAS Transmitter-Receiver	ATA 34-40-49

Additional dash numbers to existing approved components:

822-1710-411	WRT-2100 Receiver Transmitter	ATA 34-40-58
822-2127-003	RTM-2100 Receiver Transmitter Module	ATA 34-42-11
822-2131-003	DVR-2120 Radar Drive Assembly	ATA 34-42-12

8. 外委维修项目/Maintenance functions contracted to outside agencies

Component replacement on select Communication (Satcom) and Navigation (Radar) equipment.

Item No	Part No	Description	ATA Chapter	OEM	Maintenance Function	Technical Data	Major Equipment	Remark
1	822-1261-101	FCC-703 FLIGHT CONTROL COMPUTER	22-11-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
1	822-1261-102	FCC-703 FLIGHT CONTROL COMPUTER	22-11-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
2	822-0407-101	BCA-770 BACKDRIVE CONTROL ACTUATOR	22-12-74	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	BCA Bench	
3	822-1567-101	MCP-730 MODE CONTROL PANEL	22-12-82	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
3	822-1567-102	MCP-730 MODE CONTROL PANEL	22-12-82	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
4	822-1604-101	FCC-730 FLIGHT CONTROL COMPUTER	22-12-93	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
4	822-1604-102	FCC-730 FLIGHT CONTROL COMPUTER	22-12-93	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
4	822-1604-151	FCC-730 FLIGHT CONTROL COMPUTER	22-12-93	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
4	822-1604-152	FCC-730 FLIGHT CONTROL COMPUTER	22-12-93	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
5	622-5272-001	HFS-700 HF RECEIVER-TRANSMITTER	23-10-70	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
5	622-5272-003	HFS-700 HF RECEIVER-TRANSMITTER	23-10-70	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
6	622-5272-020	HFS-700 HF RECEIVER-TRANSMITTER	23-10-74	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
6	622-5272-023	HFS-700 HF RECEIVER-TRANSMITTER	23-10-74	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
6	622-5272-120	HFS-700 HF RECEIVER-TRANSMITTER	23-10-74	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
7	822-0990-001	HFS-900D HF DATA RADIO	23-11-83	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
7	822-0990-002	HFS-900D HF DATA RADIO	23-11-83	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
7	822-0990-003	HFS-900D HF DATA RADIO	23-11-83	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
7	822-0990-004	HFS-900D HF DATA RADIO	23-11-83	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
7	822-0990-020	HFS-900D HF DATA RADIO	23-11-83	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
8	822-0987-120	CPL-920D HF ANTENNA COUPLER	23-11-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
9	822-0990-120	HFS-900D HF DATA RADIO	23-11-96	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	
10	822-0987-001	CPL-920D HF ANTENNA COUPLER	23-11-97	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
10	822-0987-002	CPL-920D HF ANTENNA COUPLER	23-11-97	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
10	822-0987-003	CPL-920D HF ANTENNA COUPLER	23-11-97	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
10	822-0987-004	CPL-920D HF ANTENNA COUPLER	23-11-97	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
10	822-0987-020	CPL-920D HF ANTENNA COUPLER	23-11-97	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
11	822-2211-101	TCP-2100 TUNNING CONTROL PANEL	23-12-02	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
12	822-1047-002	VHF-900B VHF COMMUNICATIONS TRANSCIEVER	23-12-90	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000	

12	822-1047-003	VHF-900B VHF COMMUNICATIONS TRANSCIVER	23-12-90	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
12	822-1047-010	VHF-900B VHF COMMUNICATIONS TRANSCIVER	23-12-90	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
12	822-1047-020	VHF-900B VHF COMMUNICATIONS TRANSCIVER	23-12-90	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
12	822-1047-030	VHF-900B VHF COMMUNICATIONS TRANSCIVER	23-12-90	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
12	822-1047-220	VHF-900B VHF COMMUNICATIONS TRANSCIVER	23-12-90	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
13	822-1287-101	VHF-2100 VHF TRANSCIVER	23-12-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
13	822-1287-120	VHF-2100 VHF TRANSCIVER	23-12-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
13	822-1287-121	VHF-2100 VHF TRANSCIVER	23-12-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
13	822-1287-180	VHF-2100 VHF TRANSCIVER	23-12-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
14	822-1250-001	VHF-920 VHF COMMUNICATIONS TRANSCIVER	23-12-96	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
14	822-1250-002	VHF-920 VHF COMMUNICATIONS TRANSCIVER	23-12-96	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
14	822-1250-020	VHF-920 VHF COMMUNICATIONS TRANSCIVER	23-12-96	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
14	822-1250-021	VHF-920 VHF COMMUNICATIONS TRANSCIVER	23-12-96	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
15	622-8850-200	HPA-900 HIGH POWER AMPLIFIER	23-29-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
15	622-8850-201	HPA-900 HIGH POWER AMPLIFIER	23-29-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
16	822-2023-001	SRT-2100 SATELLITE DATA UNIT	23-29-30	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
16	822-2023-002	SRT-2100 SATELLITE DATA UNIT	23-29-30	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
16	822-2023-101	SRT-2100 SATELLITE DATA UNIT	23-29-30	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
16	822-2023-401	SRT-2100 SATELLITE DATA UNIT	23-29-30	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
17	822-1405-001	SRT-2000-3 SATELLITE DATA UNIT	23-29-78	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
17	822-1405-401	SRT-2000-3 SATELLITE DATA UNIT	23-29-78	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
18	622-8850-001	HPA-900 HIGH POWER AMPLIFIER	23-29-92	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
19	622-8850-100	HPA-900 HIGH POWER AMPLIFIER	23-29-98	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
20	822-1033-100	EAP-703 ENGINE AND ALERT PROCESSOR	31-41-86	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700
21	822-3253-101	DPC-2120 Display Processing Computer	31-41-92	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RCTS-4000
22	822-3252-101	DCP-2120 DISPLAY CONTROL PANEL	31-41-83	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RCTS-4000
23	822-2148-101	AFD-2100 ADAPTIVE FLIGHT DISPLAY	31-61-01	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
23	822-2148-102	AFD-2100 ADAPTIVE FLIGHT DISPLAY	31-61-01	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
24	822-2154-101	DCP-2100 DISPLAY CONTROL PANEL	31-61-02	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
24	822-2154-201	DCP-2100 DISPLAY CONTROL PANEL	31-61-02	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701

25	822-2153-101	MKP-2100 MULTIFUNCTION KEYPAD	31-61-03	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
26	822-2149-101	GGM-2100 GRAPHICS GENERATOR MODULE	31-61-04	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
26	822-2149-102	GGM-2100 GRAPHICS GENERATOR MODULE	31-61-04	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701	
27	822-3250-101	AFD-2120 Adaptive Flight Display	31-61-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RICTS-4000	
28	622-9436-100	FP-701E ELECTRONIC FLIGHT INSTRUMENT PROCESSOR	34-22-20	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
28	622-9436-101	FP-701E ELECTRONIC FLIGHT INSTRUMENT PROCESSOR	34-22-20	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-501	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-502	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-503	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-504	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-601	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-602	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
29	622-5001-701	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-104	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-107	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-108	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-109	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-110	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-111	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-112	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
30	622-5001-113	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-73	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
31	622-5001-003	RDMI-743 RADIO DISTANCE MAGNETIC INDICATOR	34-22-75	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700	
32	822-0761-001	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-003	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-004	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-007	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-008	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-010	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-011	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	
32	822-0761-012	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench	

32	822-0781-101	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
32	822-0781-201	51RV-5B VOR/ILS NAVIGATION RECEIVER	34-35-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
33	822-2911-021	TTR-2100 TCAS TRANSMITTER-RECEIVER	34-40-49	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
34	822-1710-001	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-002	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-202	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-203	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-213	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-301	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-311	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
34	822-1710-411	WRT-2100 RECEIVER TRANSMITTER	34-40-58	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
35	622-5135-801	MOUNT, ANTENNA-WMA-701X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
35	622-5135-802	MOUNT, ANTENNA-WMA-701X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
35	622-5135-821	MOUNT, ANTENNA-WMA-701X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
35	622-5135-822	MOUNT, ANTENNA-WMA-701X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
35	622-5135-823	MOUNT, ANTENNA-WMA-701X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
36	622-5136-801	MOUNT, ANTENNA-WMA-702X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
36	622-5136-802	MOUNT, ANTENNA-WMA-702X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
36	622-5136-803	MOUNT, ANTENNA-WMA-702X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
36	622-5136-821	MOUNT, ANTENNA-WMA-702X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
36	622-5136-822	MOUNT, ANTENNA-WMA-702X	34-40-59	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
36	622-5136-823	MOUNT, ANTENNA-WMA-702X	34-42-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	PTS-3100A
37	822-2120-101	ISS-2100 INTEGRATED SURVEILLANCE SYSTEM PROCESSOR	34-42-10	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
38	822-2127-001	RTM-2100 RECEIVER TRANSMITTER MODULE	34-42-11	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
38	822-2127-002	RTM-2100 RECEIVER TRANSMITTER MODULE	34-42-11	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
38	822-2127-003	RTM-2100 RECEIVER TRANSMITTER MODULE	34-42-11	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
39	822-2131-001	DVR-2120 RADAR DRIVE ASSEMBLY	34-42-12	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
39	822-2131-002	DVR-2120 RADAR DRIVE ASSEMBLY	34-42-12	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
39	822-2131-003	DVR-2120 RADAR DRIVE ASSEMBLY	34-42-12	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
40	622-5129-002	WCP-701 CONTROL PANEL	34-45-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench

49	622-5135-402	MOUNT, ANTENNA-WIMA-701X	34-45-49	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
50	622-5129-401	WCP-701 CONTROL PANEL	34-45-50	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
51	622-5129-802	WCP-701 CONTROL PANEL	34-45-52	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
52	622-5137-601	WFA-701X ANTENNA FLAT PLATE	34-45-53	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
53	622-5773-001	RAI-742 RADIO ALTITUDE INDICATOR	34-47-71	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-700
54	822-0334-002	LRA-900 RADIO ALTIMETER	34-47-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
54	822-0334-003	LRA-900 RADIO ALTIMETER	34-47-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
54	822-0334-020	LRA-900 RADIO ALTIMETER	34-47-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
54	822-0334-220	LRA-900 RADIO ALTIMETER	34-47-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
54	822-0334-221	LRA-900 RADIO ALTIMETER	34-47-95	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
55	822-1338-001	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
55	822-1338-002	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
55	822-1338-003	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
55	822-1338-004	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
55	822-1338-005	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
55	822-1338-020	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
55	822-1338-021	TPR-901 ATC/MODE S TRANSPONDER	34-50-99	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-900
56	622-6829-001	DFF-712 ADF FREQUENCY PANEL	34-53-75	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
56	622-6829-021	DFF-712 ADF FREQUENCY PANEL	34-53-75	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
56	622-6829-022	DFF-712 ADF FREQUENCY PANEL	34-53-75	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
57	822-0299-001	ADF-900 ADF RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
57	822-0299-020	ADF-900 ADF RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
57	822-0299-220	ADF-900 ADF RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
57	822-0299-420	ADF-900 ADF RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
58	822-0297-001	VOR-900 NAVIGATION RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
58	822-0297-020	VOR-900 NAVIGATION RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
58	822-0297-220	VOR-900 NAVIGATION RECEIVER	34-53-94	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
59	822-1152-001	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-002	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-003	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000

59	822-1152-004	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-005	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-120	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-121	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-122	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-130	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-131	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
59	822-1152-220	GLU-920 GLOBAL LANDING UNIT RECEIVER	34-70-09	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-001	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-002	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-130	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-330	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-331	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-332	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
60	822-1821-430	GLU-925 GLOBAL LANDING UNIT	34-70-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	RFT-1000
61	822-2100-101	AFDX-2100 AFDX CCR SWITCH	42-20-06	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
62	822-2102-101	AFDX-2120 AFDX REMOTE SWITCH	42-30-02	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
63	822-0998-101	MAT-980 Maintenance Access Terminal	45-11-13	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
63	822-0998-102	MAT-980 Maintenance Access Terminal	45-11-13	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
64	822-1197-101	LRM, Mass Memory HDD-980	45-11-14	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
65	822-1817-101	HDD-2000 Maintenance Access Terminal	45-11-15	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
66	822-1824-101	LRM, MASS MEMORY - HDD-2000	45-11-16	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
67	822-2244-101	FSM-2200 FILE SERVER MODULE	46-11-46	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
67	822-2244-151	FSM-2200 FILE SERVER MODULE	46-11-46	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
68	822-2016-102	ABM-2100 AIR BLOCKING MODULE	46-11-47	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
69	822-2280-101	MCA-2200 MODULAR CHASSIS ASSEMBLY	46-11-47	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	Manual Bench
70	822-2279-102	NIM-2200 NETWORK INTERFACE MODULE	46-11-48	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701
71	822-2242-101	EGM-2200 ETHERNET GATEWAY MODULE	46-11-49	Rockwell Collins	Inspection, repair, modification, Overhaul	OEM CMM	ITS-701

This capability list is being submitted as part of our Certificate renewal. The update includes removing all TTR-921, 822-1293-XXX part numbers. The update includes adding the following dash numbers to existing part approvals: 822-1710-411 (WRT02100 Receiver Transmitter ATA 34-40-58); 822-2127-003 (RTM-2100 Receiver Transmitter Module ATA 34-42-11); 822-2131-003 (DVR-2120 Radar Drive Assembly ATA 34-42-12). The update also includes the following part numbers added to support the new 737Max aircraft deliveries to existing customers: NOTE: 822-3253-101 and the 822-3250-101 are already covered in our FAA Approved Instrument Class 4 Rating; the 822-2911-021 is already covered in our FAA Approved Radio Class 3 rating. See attached FAA Operations Specifications. 822-3253-101 DPC-2120 Display Processing Computer ATA 31-41-92; DCP-2120 Display Control Panel ATA 31-41-93; 822-3250-101 AFD-2120 Adaptive Flight Display ATA 31-61-14; 822-2911-021 TTR-2100 TCAS Transmitter-Receiver ATA 34-40-49

