

中国民用航空局 CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

维修许可证

MAINTENANCE ORGANIZATION CERTIFICATE

编号/No.	F00100577
--------	-----------

单位名称/NAME OF ORGANIZATION:

Rockwell Collins, Inc.

单位地址/BUSINESS ADDRESS:

2051 Airport Road Wichita Kansas 67209-1949 USA

经审查,该单位符合中国民用航空规章第 145 部的要求,可以从事如下类别的维修工作:

经单查,该单位符合中国民用机至规章第145部的要求,可以从事如下实别的维修工作: Upon finding that the organization complies with the requirements of **CHINA CIVIL AVIATION REGULATION(CCAR)** Part 145, the above organization is adequate to accomplish maintenance of the following ratings:

Component Maintenance

- ☆ -

本许可证除被放弃、暂停或吊销,在下述期限内将一直有效。 This certificate, unless cancelled, suspended, or revoked, shall continue in effect until:

2025-12-31

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:

XUE Shijun

职务/Position:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

再次颁发日期/DATE REISSUED:



中国民用航空局 CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目

LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 F00100577 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F00100577 is/are limited to the following:

LOCATION: Wichita Kansas

Inspection, Repair, Overhaul and Modification of the following Components:

Auto Flight (ATA-22): Limit to 2200 Auto Flight System; 2210 Autopilot System; 2212 Altitude Controller; 2216 Autopilot Trim Servo; 2220 Speed-Attitude Correction System; 2250 Aerodynamic Load Alleviating.

Communications (ATA-23): Limit to 2300 Communications System; 2310 HF Communications System; 2311 UHF Communications System; 2312 VHF Communications System; 2320 Data Transmission Auto Call; 2350 Audio Integrating System.

Instruments (ATA-31): Limit to 3100 Indicating/Recording System; 3130 Data Recorders (Flight/Maintenance); 3140 Central Computers; 3160 Central Display.

Navigation (ATA-34): Limit to 3400 Navigation System; 3418 Stall Warning System; 3420 Attitude and Direction Data System; 3421 Attitude Gyro and Indicating System; 3425 Integrated Flight System; 3432 Glide Slope System; 3435 Heads Up Display System; 3436 Wind Shear Detection System; 3440 Independent Position Determining System; 3443 Doppler System; 3444 Ground Proximity System; 3445 Air Collision Avoidance System; 3450 Dependent Position Determining System; 3452 ATC Transponder System; 3453 Long-Range Navigation (LORAN) System; 3454 Visual Omnirange (VOR) System; 3455 Automatic Direction Finder (ADF) System; 3460 Flight Management Computing Hardware System.

颁发日期冮

(To Be Continued)

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:	À 11 -
XUE Shijun	Fry EV
职务/Position:	

Deputy Director General of FSD



中国民用航空局 CIVIL AVIATION ADMINISTRATION OF CHINA (CAAC)

许可维修项目

LIMITATION OF MAINTENANCE ITEMS

限定/LIMITATION:

对第 F00100577 号许可证所列维修类别限定如下地点和项目:

Location and items set forth on Maintenance Organization Certificate No. F00100577 is/are limited to the following:

LOCATION: Wichita Kansas (Continued)

Inspection, Repair, Overhaul and Modification of the following Components:

Cabin Systems (ATA-44): Limit to Cabin Systems.

Information Systems (ATA-46): Limit to Information Systems. Detail as listed in CAAC component maintenance capability list.

- ☆ -

局长授权/FOR THE ADMINISTRATOR OF CAAC

签字/SIGNATURE:	en g	
XUE Shijun	True 12	
	10.	

职务/Position:

Deputy Director General of FSD

颁发日期/DATE ISSUED:

2012-05-30

再次颁发日期/DATE REISSUED:

2023-08-20