Production Discontinuance Bulletin TVI-920/920D

Summary

Effective March 31, 2016 Rockwell Collins will discontinue production deliveries of the TVI-920/920D TCAS/Vertical Speed Indicator part numbers 622-9353-XXX (TVI-920) and 622-9728-XXX (TVI-920D), due to obsolescence of key LCD display components.

Am I affected?

Rockwell Collins will discontinue production of the following parts starting on the date below.

		Date of discontinuance	
Product	Part number	Production	Support
TVI-920	622-9353-XXX	March 31, 2016	Continued
TVI-920D	622-9728-XXX	March 31, 2016	Continued

Rockwell Collins may still be able to offer assistance in troubleshooting and repairing many of the affected LRUs on a parts available basis. Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

For customers interested in maintaining the TVI-920/920D on their aircraft, Rockwell Collins has several options to help.

Participate in our Last Time Buy

Customers interested in participating in a Last Time Buy should submit a purchase order before March 31, 2016 with delivery by July 31, 2016. Limited production inventory is available, Rockwell Collins will deliver while supplies last.

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at http://www.rockwellcollins.com/intertrade/index. asp.

For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins 400 Collins Road NE Cedar Rapids, Iowa 52498 319.295.4085 fax: 319.295.2297

email: csmarketing@rockwellcollins.com

www.rockwellcollins.com

