

# Production and Guaranteed Repair Discontinuance Bulletin

Navigation Indicators IND-351, RMI-30, RMI-36, 332C-10, 332D-11A, BDI-36, IND-31C

## Summary

Rockwell Collins will discontinue production of the Navigation IND-351 and discontinue support of the 332C-10, 332D-11A, BDI-36, IND-31C, RMI-30 and RMI-36 due to obsolescence of key components.

We will continue to provide the service and support you have come to expect from Rockwell Collins on a parts available basis. Additionally, Rockwell Collins may still be able to offer assistance in troubleshooting and repairing this product.

## Am I affected?

The following parts will discontinue production and support as indicated in the table below.

Product	Part number	Production Discontinuance	Support Discontinuance
332C-10	622-0555-0XX	Prior to June 2016	June 2016
332D-11A	522-3985-001	Prior to June 2016	June 2016
BDI-36	622-3702-0XX	Prior to June 2016	June 2016
BIA-32 ADPT	622-8613-001	Prior to June 2016	June 2016
BIA-32 ADPT	622-8613-002	Prior to June 2016	June 2016
CAD-31 ADPT	622-8332-001	Prior to June 2016	June 2016
IND-31C	622-4483-001	Prior to June 2016	June 2016
IND-31C	622-4483-002	Prior to June 2016	June 2016
IND-31C	622-4483-003	Prior to June 2016	June 2016
IND-351	622-2083-00X	June 2016	TBD
RMI-30	622-4938-0XX	June 2016	March 2017
RMI-36	622-2506-XXX	June 2016	March 2017

Rockwell Collins will still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product.

In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

## What are my options?

### Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, [intertradesales@rockwellcollins.com](mailto:intertradesales@rockwellcollins.com), or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

**Rockwell  
Collins**

Building trust every day



How can we help?  
Please call Rockwell Collins Customer Support at  
+1.319.295.5000.

### **Building trust every day.**

Rockwell Collins delivers innovative aviation and high-integrity solutions to commercial and government customers worldwide. Backed by a global network of service and support, we stand committed to putting technology and practical innovation to work for you whenever and wherever you need us. In this way, working together, we build trust. Every day.

For more information, contact:  
Rockwell Collins  
400 Collins Road NE  
Cedar Rapids, Iowa 52498  
+1.319.295.4085  
email: [csmarketing@rockwellcollins.com](mailto:csmarketing@rockwellcollins.com)  
[www.rockwellcollins.com](http://www.rockwellcollins.com)