

Production and Guaranteed Repair Discontinuance Bulletin

Various Federated Components

Summary

Those who are still flying with federated Rockwell Collins systems in their fleet will see the end of production for several components and the end of service for several already out of production items.

Am I affected?

The following parts will discontinue production starting on the date below.

Product	Part number	Date of discontinuance	
		Production	Support
NAC-80	229-0324-010	10/1/2016	10/1/2024
LAC-80	229-0324-020	10/1/2015	10/1/2020
YRS-65	270-0930-010	10/1/2016	10/1/2021
ALI-80A	622-3975-014	10/1/2016	10/1/2021
MAP-65	622-5799-104	10/1/2015	10/1/2020
FDU-70	622-5812-006	10/1/2016	10/1/2019
EFD-85	622-6020-021	10/1/2016	10/1/2021
EFD-85	622-6020-022	10/1/2016	10/15/2025
CCU-65	622-6135-001	10/1/2015	10/1/2020
CCU-65	622-6135-011	10/1/2015	10/1/2025
CCU-65	622-6135-014	10/1/2015	10/1/2025
DGS-65	622-6136-002	10/1/2016	10/1/2025
RCP-65	622-6174-001	10/1/2015	10/1/2025
EFD-74	622-6197-001	10/1/2016	10/1/2021
HPU-74A	622-6199-001	10/1/2016	10/1/2021
HCP-74	622-6200-002	10/1/2015	10/1/2020
APP-85	622-6208-044	10/1/2017	10/1/2022
ADS-65C	622-6332-001	10/1/2016	10/1/2025
IMT-85	622-6878-001	10/1/2015	10/1/2024
CHP-85D	622-6898-001	10/1/2016	10/1/2025
CHP-86B	622-6899-001	10/1/2015	10/1/2020
FMM-85	622-7154-001	10/1/2015	10/1/2020
FMM-85	622-7154-002	1/1/2018	10/1/2026
DPU-85G	622-7448-013	10/1/2017	10/1/2025
MPU-85G	622-7454-013	10/1/2016	10/1/2026
MFD-85B	622-7876-011	10/1/2016	10/1/2021
MFD-85B	622-7876-012	10/1/2016	10/1/2026
ADC-85	622-8051-003	10/1/2016	10/1/2021
ADC-85	622-8051-005	10/1/2016	10/1/2021
FDU-70A	622-8154-001	10/1/2015	10/1/2020
DPU-85N	622-8678-004	10/1/2016	10/1/2025
DPU-85N	622-8678-008	10/1/2016	10/1/2025

MPU-85N	622-8679-004	10/1/2016	10/1/2021
MPU-85N	622-8679-008	10/1/2016	10/1/2025
DCP-85G	622-8680-001	10/1/2016	10/1/2025
ADM-85	622-8692-008	10/1/2015	10/1/2020
ADM-85	622-8962-008	10/1/2015	10/1/2020
PRE-80C	622-9462-024	10/1/2016	10/1/2024
PRE-80C	622-9462-035	10/1/2016	10/1/2020
EFD-84	622-9681-001	10/1/2016	10/1/2021
EFD-84	622-9681-102	10/1/2015	10/1/2020
DPU-84	622-9682-004	10/15/2015	10/1/2022
DSP-84	622-9683-221	10/1/2015	10/1/2020
DSP-85M	822-0967-201	10/1/2015	10/1/2020
ADC-87A	822-1398-170	10/1/2015	10/1/2025
DCP-85E	622-6794-001	10/1/2015	10/1/2020

Rockwell Collins may still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

Participate in our Last Time Buy

For customers interested in maintaining a federated product within their fleets, Rockwell Collins has several options to help.

Customers interested in participating in a Last Time Buy should submit a purchase order by May 1, 2016, with delivery by Sep. 30, 2016.

Upgrade to an Integrated System

For customers seeking a highly capable solution to the federated discontinuance, Rockwell Collins produces many options for an integrated system ready for tomorrow's demanding airspace requirements.

For more information about which system is best for your needs and aircraft, please contact Rockwell Collins Marketing at csmarketing@rockwellcollins.com.

**Rockwell
Collins**

Building trust every day

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

For more information, contact your
Regional Sales Manager:

Please call Rockwell Collins Customer
Support at +1.319.295.5000.

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
319.295.4085
fax: 319.295.2297
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day