

Production and Guaranteed Repair Discontinuance Bulletin

Former International Communications Group (ICG) Products

Summary

Related to the acquisition of International Communications Group (ICG), Rockwell Collins has reviewed all of the part numbers listed in the ICG catalog and has removed the obsolete part numbers.

In most cases, this is a formal notification of a product that has been out of production, or not serviceable for some time. There are some cases where Rockwell Collins has decided to end production as a result of parts obsolescence, or where there has been no market activity for an extended period.

Am I affected?

The following parts discontinued production on December 31, 2015.

Product Category	Part Number
Misc. Accessories	
Accessory	214210
Accessory	501727
Accessory	938035-00-4
Install Kit	938500-200
Install Kit	744618
Accessory	400318
Install Kit	400618
Pass Through items	
Accessory	PTA12-104
Install Kit	2322-B43-K107
Install Kit	2322-B43-K113
Install Kit	2854674K-1-05
Install Kit	2912676K-1-07
Accessory	500803-1
Accessory	500804-1
Accessory	724986-802
AeroCom 3000	
CTU	350000-00-010200
CTU	350000-00-A10200
CTU	350000-10-B20210
CTU	936000-2

Iridium Transceivers

Iridium Transceiver	720616-2
Iridium Transceiver	730617-2
Iridium Transceiver	740617-2
Iridium Transceiver	400101-2
Iridium Transceiver	400102-2
Iridium Transceiver	400103-2

Sigma 7

Handset	500040-00-00
Handset	500040-00-02
Handset	500040-20-02
Handset	500066-0
Handset	500066-1
Handset	500066-2
Handset	500066-3
Handset	500905-10-10-1
Handset	500905-10-10-1Z Replaced by 500905-10-10
Handset	500905-10-11-1
Handset	500905-10-12-1 Replaced by 500905-10-12
Handset	500905-20-01-1
Handset	500905-20-02-1
Handset	500905-20-40-1
Handset	500905-20-41-1
Handset	500905-20-42-1
Handset	744000-00-00
Handset	744000-00-02
Handset	744000-10-10
Handset	744000-10-11
Handset	744000-10-12
Handset	744000-20-00
Handset	744000-20-02

JetPhone

Handset	938801A-B Replaced by 938811A-B
---------	------------------------------------

DECT Cordless

Handset	463092-110*
Handset	463092-120*
Handset	463092-240*
Handset	463092-250*

*DECT Phones replaced by ePhone Series in most installations.

Ethernet Switch

Router	794000-2
--------	----------

The following parts discontinued service starting on December 31, 2015.

Product	Part Number
---------	-------------

Misc. Accessories

Accessory	248600
Accessory	248601
Accessory	248602
Accessory	500990
Antenna	370103
Accessory	700301
Accessory	700302
Accessory	700303
Accessory	700304
Accessory	794304
Accessory	794305
Accessory	937080
Accessory	937081
Antenna	220107
Install Kit	744618

AeroCom 2200

CTU	220000-001
CTU	220000-011
CTU	220000-101

AeroCom 3000

CTU	350000-00-000000
CTU	350000-00-010210
CTU	350000-00-011000
CTU	350000-00-012000
CTU	350000-00-021000
CTU	350000-00-A10001
CTU	350000-00-A10210
CTU	350000-00-A11000
CTU	350000-00-A11001
CTU	350000-00-A20000
CTU	350000-00-A20001

CTU	350000-00-B10000
CTU	350000-00-B20000
CTU	350000-00-B20200
CTU	350000-00-B20210
CTU	350000-10-A10000
CTU	350000-10-A10001
CTU	350000-10-A11000
CTU	350000-10-A11001
CTU	350000-10-B10000
CTU	351000-00-B10040

AeroCom Install Kit

Install Kit	938506-110
Install Kit	938600-000
Install Kit	938600-010
Install Kit	938600-100
Install Kit	938600-110

NxtMail Server

Router	370000-00
Router	370000-10

Sigma 7

Handset	500040-00-00-1
Handset	500040-00-01
Handset	500040-00-02-1
Handset	500040-00-20
Handset	500040-00-22
Handset	500040-00-32
Handset	500040-00-33
Handset	500040-00-40-1
Handset	500040-00-42-1
Handset	500040-00-43-1
Handset	500040-10-11
Handset	500040-10-12
Handset	500040-11-10
Handset	500040-11-11
Handset	500040-11-12
Handset	500040-20-00
Handset	500040-20-01
Handset	500041-00-00
Handset	500041-00-01
Handset	500041-00-02
Handset	500041-00-03
Handset	500041-10-01
Handset	500041-10-02
Handset	500041-10-03
Handset	500044-00-00-1

Handset	500044-00-02-1
Handset	500044-00-03-1
Handset	500044-00-40-1
Handset	500068-1
Handset	500905-00-00-1
Handset	500905-00-03
Handset	500905-10-10-1Z
Handset	500905-10-13-1
Handset	500905-11-10-1
Handset	500905-11-12-1
Handset	500905-11-13-1
Handset	500905-20-00
Handset	500905-20-00-1
Handset	500905-20-03-1
Handset	500905-20-43-1
Handset	500905-20-92-1
Handset	744000-00-62
Handset	744000-11-10
Handset	744000-11-12
Handset	744000-20-40
Handset	744000-20-42
Handset	744000-20-62
Handset	744000-21-00
Handset	744000-21-02

Siemens Handsets

Handset	500092-110
Handset	500092-111
Handset	500092-200
Handset	500092-210
Handset	500092-211
Handset	500092-215
Handset	500092-217509

Jetphone

Handset	938801A-B
Handset	938801A-Colors
Handset	938810C-Colors
Handset	9388113A-Colors
Handset	938811C-Colors
Handset	9L8801A-Colors
Handset	9L8811A-Colors

DECT Cordless

Handset	463091-XXX
Handset	463092-100
Handset	463092-110
Handset	463092-111

Handset	463092-112
Handset	463092-113
Handset	463092-120
Handset	463092-121
Handset	463092-122
Handset	463092-123
Handset	463092-130
Handset	463092-140
Handset	463092-150
Handset	463092-200
Handset	463092-202
Handset	463092-230
Handset	463092-240
Handset	463092-242
Handset	463092-250
Handset	463093-120
Handset	463093-200
Handset	463094-120
Handset	463095-220
Handset	463095-222
Handset	463096-120
Handset	463096-121
Handset	463096-122
Handset	463096-123
Handset	463096-124
Handset	463096-125

Handset Accessories

Accessory	737015
Accessory	500405

Ringers

Accessory	938035-10-3
Accessory	938035-10-4
Accessory	938065-00-1

Iridium Transceivers

Iridium Transceiver	500616-2
Iridium Transceiver	500616-2-1
Iridium Transceiver	500616-3
Iridium Transceiver	500617-2
Iridium Transceiver	500617-2-1
Iridium Transceiver	500617-3
Iridium Transceiver	500617-4
Iridium Transceiver	500617-4-1
Iridium Transceiver	500617-5
Iridium Transceiver	500617-5-1
Iridium Transceiver	710101-2

Iridium Transceiver	710616-1
Iridium Transceiver	710617-1
Iridium Transceiver	720617-2
Iridium Transceiver	730616-2
Iridium Transceiver	400000-0-000
Iridium Transceiver	400000-0-001
Iridium Transceiver	400000-0-010
Iridium Transceiver	400000-0-100
Iridium Transceiver	400000-0-101
Iridium Transceiver	400000-0-110

CIM Reader

CIM Reader	329100
------------	--------

NxtLink Install Kits

Install Kit	700618-2
Install Kit	700618-3
Accessory	710906
Install Kit	500618
Install Kit	500618-2

CIS-100

Iridium Transceiver	247000-0
Iridium Transceiver	247000-1
Iridium Transceiver	247000-2-0

CIS-100 Install Kits

Install Kit	247618
Install Kit	247618-1
Install Kit	247618-2

Antennas

Antenna	500644
Antenna	500644-1
Antenna	500644-3
Antenna	500644-4
Antenna	500644-5
Antenna	500644-6
Antenna	567-1575-163

Pass Through (Gables)

Accessory	G7164-01
Accessory	G7164-06
Accessory	G7164-07

STC Install Kits

Install Kit	28546-74K-1
Install Kit	2854674K-1-01
Install Kit	2854674K-1-03

Install Kit	2854674K-1-09
Install Kit	2912676K1
Install Kit	2912676K2
Install Kit	2322-B43-K-109

PTA-12 Dialer

Accessory	500803
Accessory	500804
Accessory	500805
Accessory	PTA12-104

MIS-200

Iridium Transceiver	249000
Install Kit	248618

Rockwell Collins will still be able to offer assistance in troubleshooting and repairing many of the affected LRUs. However, Rockwell Collins reserves the right to decline a request for service and/or a request for quote to repair the affected product. In addition, while Rockwell Collins may agree to attempt to repair a product, it does not guarantee the repair can be completed. In the event it is determined the product is beyond Rockwell Collins' repair capabilities the product will be returned in 'as-is' condition.

What are my options?

Contact Intertrade for used equipment

Rockwell Collins Intertrade, a buyer and seller of used equipment, may have used product available should any LRU be deemed un-repairable. For more information contact Rockwell Collins Intertrade at 1.319.378.3500, intertradesales@rockwellcollins.com, or on the web at <http://www.rockwellcollins.com/intertrade/index.asp>.

Consider a different version

In many cases, there may be a similar, or even upgraded, product available to use as an alternate part.

Contact your Rockwell Collins Regional Sales Manager to see if an acceptable alternate is available.

For more information, contact your Regional Sales Manager:

Please call Rockwell Collins Customer Support at +1.319.295.5000.

Rockwell Collins
400 Collins Road NE
Cedar Rapids, Iowa 52498
319.295.4085
fax: 319.295.2297
email: csmarketing@rockwellcollins.com
www.rockwellcollins.com

**Rockwell
Collins**

Building trust every day